

WING Firmware 3.1.2 Release Notes

Changed

- Improved indication of whether a send fader's pan control is linked to the channel pan

Fixed

- Some Dante expansion cards failed to boot when used with BK3 modules and Dante firmware 4.3.1.8
- Reordering channel processing slots could increase latency